



Looking North. Vehicle operators must use extreme caution when crossing runway especially when the tower is not operating.



Looking north. Intersection of east parallel taxiway and Runway 36

Airport Operations:	(913) 782-1245
Air Traffic Control:	(913) 782-2192
Hours of Operation:	Airport: 24 hours Tower: 0700-2100 local
Latitude:	38 degrees 50.86
Longitude:	94 degrees 13' 44.26'
Elevation:	1096 ft.
Variation:	4 E degrees
Sectional Chart:	Kansas City
Control Tower:	Yes
ARTCC:	Kansas City Center
FSS:	1-800-992-7433
NOTAM Facility:	Columbia FSS
Wind Indicator:	Yes
Beacon:	Yes
Fire and Rescue:	No
Airline Operations:	No
Customs:	No
UNICOM:	122.95
CTAF	126.0
ATIS:	119.35
OJC Ground:	121.6
OJC Tower:	126.0
Clearance Delivery:	121.6
Approach Control	118.9
ASOS	(913) 780-6969
VOR	113.0
RCO	122.15



AIRPORT RUNWAY SAFETY INFORMATION

Johnson County Executive Airport (OJC) (revised)

October 2002

RUNWAY SAFETY
Everyone's Responsibility
STAY ALERT!

FEDERAL AVIATION ADMINISTRATION
Central Region Runway Safety Program
<http://www.faa.gov/runwaysafety>

HIGH ALERT INTERSECTIONS

- 1.** Vehicle operators must use extreme caution when crossing runway.
- 2.** Aircraft taxiing south on east parallel use caution when approaching the hold position marking for Runway 36. Hold position sign is not fully visible until aircraft has turned the corner.

